

OT-10

Hardware Quick Installation Guide



Version: 3.0

Date: 2014-9-29

General Notes:

All materials contained on this documentation is protected by the copyright law and may not be reproduced, transmitting, published or broadcast without the prior obtaining authorization of Wonde Proud Technology. The documentation is provided for testing, evaluation, integration and product information purpose and it may contain deficiencies or inadequacies information of products. This product is not intended for use in life support appliance, devices or systems where a malfunction of the product can reasonably be expected to result personal injury. Wonde Proud or its supplier will not be liable for any consequential, direct, indirect, incidental, punitive or other damages including without limitation, damages for loss of business profits, business interruption, loss of business information or other pecuniary loss that arising out the use of or inability to use the documentation or product, even if Wonde Proud has been advised of the possibility of such damages. The customers using or reselling the product in such application do so at their own risk and agree to full indemnify Wonde Proud for any damages resulting from illegal use or resale. Subject to change without notice at any time.

Copyright


Reproduction, dissemination, edition of this document, or utilization of the content and communication format as well as giving to other without authorization are prohibited. Offenders will be held liable for payment of damages.

Copyright ©Wonde Proud Technology 2007. All right are reserved.

Table of Content

1. Introduction to WondeX OT-10 Hardware	4
2. Insert the SIM Card	5
3. Micro USB Port	5
4. Charging Backup Battery	5
5. LED Indicators	6
6. About Wonde Proud Technology	7

1. Introduction to WondeX OT-10 Hardware



2. Insert the SIM Card

Please follow the steps below to insert the SIM card correctly.

1. Remove the SIM card cover.
2. Please follow the below illustration to insert the SIM card to the device in correct direction. If the SIM card is well inserted, you will hear a “click” sound.



3. Put the SIM card slot cover back to the original position.

3. Micro USB Port

- USB Cable can be used for the unit configuration only, not for charging backup battery.
- Please use the micro USB cable provided by Wonde Proud.

4. Charging Backup Battery

After connecting the OT10 to the vehicle OBDII socket. It will start charging after engine switching off. Once the backup battery is fully charged, it will not start charging every time engine switching off.

5. LED Indicators

Indicators	Blinking Behavior	Status
GSM (Amber)	Off	Entering sleeping state
	0.6 second on/ 0.6 second off	Not Ready or Searching GSM signal
	100ms on / 3 seconds off	Registered to GSM network successfully
	100ms on twice / 2.5 seconds off	GPRS is ready (Server connection is established)
GPS (Green)	1 second on / 1 seconds off	GPS not fixed
	Solid on	GPS fixed
	100ms on/ 5 seconds off	Enter Sleeping State (Except mode 3 of \$WP+PSM command)

6. About Wonde Proud Technology

WondeX VT series device is manufactured by Wonde Proud Technology. Wonde Proud Technology provides advance solution for GPS related solutions including the various GPS components, Automatic Vehicle Location (AVL) device (data logger & real time tracking devices). Please contact us at the phone and fax number list below or visit our website for further product information.



Wonde Proud Technology

Web site: <http://www.wondeproud.com>

Tel: [+886-2-26968498](tel:+886226968498)

Fax: [+886-2-26968499](tel:+886226968499)

Address: [4F., No.100,Sec.1,Shin Tai Wu Rd, Sijhih city, Taipei county 22102, Taiwan.
R.O.C](#)